

FIG. 1A




FIG. 1B




FIG. 2

65580-ETH2850




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 4C

655280-Enhanced




FIG. 4D




FIG. 4E

653280-Enhanced




FIG. 4F




FIG. 5A




FIG. 5B




FIG. 5C

665230-Enhanced




FIG. 5D




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 6E




FIG. 6G





FIG. 7

FIG. 8



**From the Active.
Initiation, and
Reconstructions**

To Active State

dicn established

Release msg sent
PPP is terminated

To Yuli

PPP is terminated

Release msg sent
PPP is not terminated

PPP is not terminated

To Dostani State

MS directed by BS to return to Montreal subsite

Stalled Hole Timer expires

Control Mod - Slotted

Control Hold - Normal

Hold Timer expires

Tc Suspended State